



TECHNICAL FIELD BULLETIN



Date February 2009
Subject Easy120V Software Revision
Document 90203-1070

OVERVIEW

The “Buy Change” feature has been removed from Easy120V safes.

PRODUCTS AND SERIAL NUMBERS AFFECTED

First Serial Number with Easy120V Version 0.72: SP2009003073.

ACTION REQUIRED

This bulletin is for information purposes only.

ADDITIONAL INFORMATION

If you have any questions contact NKL Technical Service at 1-800-452-4655.